

## **MEMORANDUM**

T0:

Cheryl Terai, CTA Branch Manager

FROM:

Mark Witherspoon, Permits Engineer (LDS)

DATE:

October 1, 1982

SUBJECT: Olin Corporation - North Little Rock Plant \_\_\_

I have reviewed the Olin Corporation reports, including the FIT report, as requested. The contamination detected in the surface and groundwater sampling appears to be a major problem in terms of potential for migration. The subsurface generally consists of 9-12 feet of slow permeability clay overlying a highly permeable sand. The static water levels are not reported in enough detail (ranges only provided) to determine groundwater flow characteristics, however, I would assume the flow direction to be southerly toward the Arkansas River.

My concern with past "landfilling" operations is that <u>excavation have gone through</u> the clay and into the permeable sand below. If this is the case, then waste could have been disposed of directly in the sand.

I also can find no record of Olin Corporation ever having (or applying for) a solid waste permit.

MW:ch

9292467

